



Car data

22:24

23.03.2015

<i>VIN Number</i>	WV2ZZZ2KZBX251087	<i>Engine Code</i>	CBZA
<i>Sales Type</i>	2CBTE2	<i>Transmission Code</i>	LSQ
<i>Model Year</i>	2011	<i>Finaldrive Ident</i>	5S
<i>Model</i>	CA	<i>Interior Trim Code</i>	NY
<i>Model Designation</i>	caddy kombi	<i>Roof Color</i>	J2
<i>Date of Production</i>	27.12.2010	<i>Exterior Color/Paint Code</i>	J2/H7J
<i>Order Number</i>			

PR Numbers

A8C	Comfort equipment
AV1	Driving on the right
B04	Type approval Denmark
B0A	Component parts set without country-specific design requirement
C32	Operating permit, alteration
C8V	Steel wheels 6J x 15
DB1	4-cylinder gas. engine 1.2 l/63 kW TSI
	Base engine is: TW0/TP1
E0A	No special edition
F0A	No special purpose vehicle, standard equipment
G0C	5-speed manual transmission
HD2	Tires 195/65 R15 91T
J1L	Battery 280 A (60 Ah)
K4B	Window van
L0L	Left-hand drive vehicle
L40	Suspension range 40
	installation control only, no requirement forecast
N0E	Woven fabric seat covering
NY0	Standard battery/alternator capacity
PL5	"Lights & Vision"
QE1	Tray areas package 1
QG1	Service interval prolongation
QL3	Heat-insulating glass (green)
QN1	Drawer under left front seat
QV0	W/o TV reception/digital radio reception
TW0	4-cylinder gasoline engine 1.2 L
	Unit 03F.B
U5A	Instrument insert, km/h speedometer
UF0	Without electric interface
UG0	Without hill hold control / hill descent control / comfort driving assist
V0A	Tires w/o specification of tire brand
WE1	Package for Denmark
ZJ7	Caddy 7-seater (Trendline/Comfortline)
0E1	Short wheelbase
0EM	Installation differentiation for transmission MQ 200 vehicle components



Car data

22:24

23.03.2015

PR Numbers

0HD	Vehicle class differentiation 2K0
0J2	Standard payload
0NB	Nameplate set in base trim
0VL	Information kit in Danish
0Y1	Standard climatic zones
0YA	Weight range 1 installation control only, no requirement forecast
1BA	Standard suspension/shock absorption
1C1	Antifreeze up to -25 degree celsius tolerance up to -30 degree C
1D0	Without trailer hitch
1EX	Special identification plate for EC for M1 passenger vehicle
1G8	Breakdown set
1HZ	Labels without country group
1NN	Full wheel covers
1PA	Standard wheel bolts
1SA	Without additional front underbody guard
1T0	Without first aid kit and warning triangle
1X0	Front wheel drive
1Z0	Initial standard fuel filling
1ZE	Disc brakes, front (Geomet D)
2A0	Without delivery equipment
2E2	15-inch chassis
2G1	Insert for the filling up of unleaded fuel
2JG	Body-colored bumpers
2KX	Labels/plates in Danish, Finnish, and Swedish
2PG	Steering wheel
2V1	Dust and pollen filter
2WA	Without additional tires
3CA	Without partition
3D6	Center console
3FA	Without roof insert (standard roof)
3H0	Without backrest release for front seats
3HA	Without leather parts scope
3L1	Manual height adjustment for left front seat
3LE	Door and side trim panel
3M3	Passenger car design
3NV	Rear seat bench, split folding (first row of seats) plus two-seater rear seat bench (second row of seats)
3RC	Trunk lid with window aperture
3S6	Roof rails preparation
3SF	Comfort seat, front right
3TF	Comfort seat, front left
3U0	Without luggage compartment cover
3W0	Without additional noise suppression measures for passenger compartment



Car data

22:24

23.03.2015

PR Numbers

4A0	Without seat heater
4DE	Fixed side window in passenger compartment front left
4EE	Fixed side window in passenger compartment front right
4FH	Fixed side window in load/passenger compartment left
4GF	Windshield in heat-insulating glass
4HH	Heated rear window
4JH	Fixed side window in load/passenger compartment right
4K3	Radio remote controlled central locking operated from inside and safe securing
4L6	Breakaway interior rear view mirror, automatically dimming
4N2	Standard dashboard
4R4	Power windows with comfort operation and circuit breaker
4SC	Left vanity mirror with cover
4TC	Right vanity mirror with cover
4UF	Driver's and front passenger air bag with front passenger air bag deactivation
4X3	Side air bag front with curtain air bag
4Z3	Lockable glove compartment door, with light
5AD	Carpet floor covering in cab
5BF	Carpet floor covering in passenger compartment
5CH	Roof interior trim, comfort molded headlining in cab and passenger compart.
5D1	Carrier frequency 433.92 MHz-434.42 Mhz
5DD	Comfort side panel trim in passenger compartment
5K5	Transit coating film with additional transport protection measures
5Q2	Sliding door left in load/passenger compartment
5R2	Sliding door right in load/passenger compartment
5RQ	Right exterior mirror: convex
5SL	Left exterior mirror: aspherical
5TC	Without decorative inserts
6EA	Without additional side body covers (stone guard)
6FF	Body-colored exterior mirror housings and various add-on parts
6KA	Radiator grille
6P8	Rear license plate bracket
6U0	Without additional seals outside
6XN	Exterior mirrors: electrically adjustable, separately heated
7A0	Without CD changer/CD player



Car data

22:24

23.03.2015

PR Numbers

7AA	Electronic vehicle immobilization device
7B2	12-volt socket in luggage boot
7L3	Without start/stop system without regenerative braking
7MG	Emission standard EU5
7Q0	Without navigation device
7QA	Without CD/DVD for navigation
7X0	Without park distance control
8GG	Alternator 110 A
8IA	Halogen headlight
8K3	Separate daytime running lights with low beam assistant and "Coming Home" feature
8M1	Rear window wiper and washer system with intermittent control
8N3	Windshield wiper intermittent control with rain sensor
8QJ	Key for locking system with remote control
8RL	6 speakers (passive)
8T0	Without cruise control system (CCS)
8UA	Radio with CD player
8W0	Without washer fluid level indicator
8WD	Integrated front fog light
8X0	Without headlight washer system
8Z5	Not hot country
9AA	Manually controlled heating system
9JA	Non-smoking package
9M0	Without auxiliary/parking heater
9P1	Seat belt reminder, electric contact in buckle
9Q0	Without multi-function display/on-board computer
9T0	Without heated washer nozzles
9W0	W/o car phone preparation/installation
9WC	Without "Multimedia" in vehicle